
FIG. 1






FIG. 3




FIG. 4A




FIG. 4B




FIG. 4C




FIG. 5




FIG. 6




FIG. 7






FIG. 8





→ WITH NO PRISM SHEET ■ WITH PRISM SHEET 100 CHANGE IN CHROMATICITY IN RESPECTIVE OUTGOING DIRECTIONS (x) OUTGOING ANGLE (deg) 20 -50 FIG. 10 -100 -0.02 -0.0150.015 0.005 -0.005 0.02 0.01 -0.01 AMOUNT OF CHANGE IN CHROMATICITY

100 CHANGE IN CHROMATICITY IN RESPECTIVE OUTGOING DIRECTIONS (x) 20 OUTGOING ANGLE (deg) -50 FIG. 11 -100 -0.02 0.015 0.005 -0.005 -0.015-0.01 0.02 0.01 0 AMOUNT OF CHANGE IN CHROMATICITY

→ WITH NO PRISM SHEET

■ WITH PRISM SHEET

FIG. 12




FIG. 13

